



## FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

BOB MARTINEZ CENTER 2600 BLAIRSTONE ROAD TALLAHASSEE, FLORIDA 32399-2400 RICK SCOTT GOVERNOR

CARLOS LOPEZ-CANTERA LT. GOVERNOR

HERSCHEL T. VINYARD JR. SECRETARY

February 27, 2014

Attn: Mr. Art Sanford Naval Facilities Engineering Command Southeast BRAC Program Management Office East 203 S. Davis Drive, Bldg 247 Joint Base Charleston, SC 29404

Subject: Final Long Term Monitoring Optimization Report, Study Area 2 (SA 2) – Herndon Annex,

Former Naval Training Center Orlando, Orlando, Florida

Dear Mr. Sanford:

I have completed my review of the Final Long Term Monitoring Optimization Report, Study Area 2 (SA 2) – Herndon Annex, Former Naval Training Center Orlando, dated November 14, 2013 (received November 19, 2013), prepared and submitted by Resolution Consultants. I have the following comments on the report:

- (1) In Table 3-2, the maximum site concentrations, GCTLs and NADCs for total dissolved solids and sulfate are incorrect. The concentrations presented are in mg/L rather than  $\mu$ g/L. Please fix the table.
- (2) In Section 3.3, second to last paragraph, last sentence, Chapter 62-770.680, F.A.C., is cited. It should be Chapter 62-780.680, F.A.C., as Chapter 62-770, F.A.C., has been repealed.
- (3) In Sections 4.1 and 4.2, the word "limited" is used incorrectly. Rather than using "limited wells" or "limited VOCs", it should written as "a limited number of wells" or "a limited number of VOCs".
- (4) In Section 6.0, third sentence, it says "Contaminants continue to impact groundwater beneath the Azalea Park neighborhood, but water use restrictions are effective in limiting exposure." Groundwater use restrictions through deed restrictions have only been implemented on former Navy property in Herndon Annex. There are no water use restrictions for the groundwater under Azalea Park. Please fix this statement.
- (5) In Section 7.5, Well Abandonment Recommendations, five active monitoring wells are recommended for abandonment. Wells OLD-02-01A and OLD-02-09A are both screened above the depths that have been determined to be contaminated. However, before the Department can agree these two wells can be abandoned, please provide a history of analysis for these wells. Wells OLD-02-12C and OLD-02-08C should be retained and should be analyzed for VOCs. These wells are screened at depths appropriate for monitoring the potential migration of PCE and TCE from well OLD-02-46DR. The Department concurs that well OLD-02-63D is no longer

Mr. Art Sanford Final Long Term Monitoring Optimization Report Study Area 2 (SA 2) Page 2 of 2 February 27, 2014

required for groundwater monitoring as clean wells OLD-02-59D, OLD-02-64D and OLD-02-65C appear suitably placed to make monitoring unnecessary. I will let you decide whether there is a benefit in keeping the well for water level measurements.

(6) Figures showing the current plume configurations for the benzene, PCE and TCE plumes would be beneficial in evaluating the conclusions and recommendations made in the report. Likewise, figures showing the potentiometric surface elevations and groundwater flow directions for different depths in the surficial aquifer would be appreciated.

If you have any concerns regarding this letter, please contact me at (850) 245-8997.

Sincerely,

David P. Grabka, P.G.

Remedial Project Manager

DoD and Brownfields Partnerships

Waste Cleanup Program

cc: Marianne Sweeney, AECOM, Orlando

! Grath

KAW